


Township 14 N. Range 10 E.

Interior Section Corners Described

Quarter Section Corners Continued

Section	Bearing	Inches	Course	Chy	Dist	Quality of the Land	Section	Bearing	Inches	Course	Chy	Dist	Section	Bearing	Inches	Course	Chy	Dist
A	N 1/2 E	18	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	25, 26, 27, 28	N 1/2 E	24	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
B	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	26, 27, 28, 29	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
C	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	27, 28, 29, 30	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
D	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	28, 29, 30, 31	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
E	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	29, 30, 31, 32	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
F	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	30, 31, 32, 33	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
G	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	31, 32, 33, 34	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
H	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	32, 33, 34, 35	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
I	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	33, 34, 35, 36	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
J	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	34, 35, 36, 37	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
K	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	35, 36, 37, 38	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
L	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	36, 37, 38, 39	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
M	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	37, 38, 39, 40	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
N	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	38, 39, 40, 41	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
O	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	39, 40, 41, 42	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
P	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	40, 41, 42, 43	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
Q	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	41, 42, 43, 44	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
R	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	42, 43, 44, 45	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
S	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	43, 44, 45, 46	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
T	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	44, 45, 46, 47	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
U	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	45, 46, 47, 48	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
V	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	46, 47, 48, 49	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
W	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	47, 48, 49, 50	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
X	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	48, 49, 50, 51	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
Y	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	49, 50, 51, 52	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24
Z	N 1/2 E	11	S 20 E	24	24	1/2 to 1/2 water bottom, Oak Hickory	50, 51, 52, 53	N 1/2 E	11	S 20 E	53	53	1/2 to 1/2	N 1/2 E	10	S 20 E	24	24



Township N°II South of the Base Line Range N°VII West of the Meridian

Scale of 40 Chains to an Inch.
Surveyed by Stephen Denton 1805.

Description of the Quality of the Land on the Interior Sectional Lines

Section	Quality	Section	Quality	Section	Quality
25, 26	Second rate land timber Oak Hickory &c.	27, 28	Generally 2 nd rate land Gum Oak &c.	12, 14	Unimproved 2 nd rate land Oak Hickory &c.
24, 25	Same	23, 24	Barren hills timber Oak Hickory &c.	16, 17	Same.
22, 24	Same	22, 20	First rate land Oak Gum Walnut &c.	9, 10	Same.
26, 25	Same	20, 29	2 nd rate upland some rich bottom Oak Hickory &c.	12, 14	Generally hilly Oak Hickory Birch &c. some rich bottom.
25, 26	Same	21, 23	Hilly 2 nd rate land Hickory Gum &c.	17, 18	2 nd rate upland Oak Hickory &c.
25, 26	Same	22, 27	Same.	7, 18	First rate upland some rich bottom little timber
11, 14	Same	23, 26	Unimproved 2 nd rate land Hickory Oak &c.	3, 17	Unimproved 1 st rate land Oak Ash Gum &c.
7, 8	Same	24, 25	Same.	1, 12	Same
6, 7	Same	21, 22	Same.	1, 2	Same
5, 8	Same	16, 21	Same.	9, 16	Hilly 2 nd rate land Oak Hickory &c.
4, 9	Same	22, 24	Same.	10, 12	Same
2, 2	Same	22, 23	Hilly 2 nd rate Oak Hickory Gum &c.	10, 11	Same.
22, 22	Same generally - some rich land	17, 20	Same.	2, 10	Same
21, 22	Same	14, 20	Same.	2, 11	Same
20, 21	Generally 1 st rate land Oak Gum &c.	12, 22	Same	12, 12	First rate upland Oak Oak Elm Sugar tree &c.
29, 22	1 st rate land No Walnut, Oak &c.	20, 21	First rate land Oak Oak Gum &c.	11, 12	Same.
23, 22	1 st rate upland Oak Hickory Gum Oak &c.	19, 20	Generally 1 st rate upland Oak Oak Elm &c.	3, 9	2 nd rate land gently uneven Oak Hickory &c.
27, 21	Unimproved 2 nd rate land Hickory Oak &c.	19, 18	2 nd rate land Oak &c. Hickory	2, 4	Generally 1 st rate upland Oak Oak Walnut &c.
26, 23	Same.	18, 16	Same.	4, 5	Some 2 nd rate bottom Maple Elm &c. some rich marsh &c.
19, 20	Same.	14, 15	Same.	5, 6	Generally 2 nd rate upland Oak Hickory &c. Oak &c.